

Audi Q2

VIN: WAUZZZGA5KA078168

Diesel

Generato su 2024-11-13 14:43



Contachilometri

✓ Sembra buono



Status legale

✓ Sembra buono



Danno


✓ Sembra buono



+31

Origine dei dati

Abbiamo controllato 900+ fonti di dati nel **35 Paese**



Partner

Questo report contiene informazioni


Rubato

Il veicolo è attualmente segnalato come rubato? Il veicolo è stato rubato in passato? È stato recuperato?

✓ Nessun problema trovato

Non abbiamo trovato alcun documento che attesti il furto del veicolo.

i Nota

Verifica sui veicoli rubati completata nel database della polizia di **9 Paesi**:  +3

Ecco cosa abbiamo trovato:



Attualmente ricercato come rubato

✓ Nessun record trovato



Rubato in passato

✓ Nessun record trovato

Stato attuale sconosciuto



Rubato in passato

✓ Nessun record trovato

Il veicolo è stato recuperato

Controllo dei veicoli rubati nel database della polizia **completato in:**



Stati Uniti



Lituania



Danimarca



Slovacchia



Romania



Slovenia



Cechia



Svezia




Finlandia

Contachilometri

Ci sono segni di alterazioni o discrepanze nel chilometraggio?

Nota

- Ultimo chilometraggio noto: 85.804 km
- 5 record di chilometraggio trovati



Dati del contachilometri

2019-08	15 km
2021-04	30.278 km
2022-06	61.695 km
2023-08	85.768 km
2024-04	85.804 km

Status legale

Il veicolo ha superato la revisione tecnica? È stato contrassegnato come rottamato?

- ✓ **Nessun problema trovato**
Non è stata trovata alcuna documentazione sullo status legale di questo veicolo

Legale



Ispezione tecnica

✓ Nessun record trovato

Non sono stati trovati documenti di ispezione tecnica



Rottame

✓ Nessun record trovato

Non risulta che il veicolo sia stato dichiarato rottamato.

Danno

Il veicolo è stato danneggiato in passato? Quanto sono stati ingenti i danni?

- ✓ **Nessun problema trovato**

Documentazione dei danni



Si possono riscontrare imprecisioni occasionali, soprattutto quando si controllano i veicoli più vecchi. Le autofficine non autorizzate possono nascondere illegalmente i difetti o i danni del veicolo, senza registrarne l'esistenza. A volte, persino le targhe dei veicoli possono essere sostituite. Disponiamo di una serie di metodi per rilevare anche questi reati, ma è impossibile fornire una garanzia al 100%.

Calamità naturale

La posizione del veicolo è stata registrata nell'area in cui si è verificata una calamità naturale?

✓ Nessun problema trovato

La posizione del veicolo non è stata registrata nell'area interessata da una calamità naturale

Valore di mercato

A quanto è stato venduto il veicolo in passato? Qual è il prezzo medio dei veicoli di questo anno e modello?

i Nota

- Ultimo prezzo di vendita noto: 24.900 €
- Prezzo medio di mercato per un veicolo di questo tipo: 22.251 €
- Attenzione ai problemi nascosti nel caso in cui il veicolo fosse in vendita a un prezzo notevolmente inferiore a quello medio!

Valore di mercato attuale di Audi Q2

Il valore di mercato viene determinato esaminando il prezzo di un particolare modello di auto (prodotto nello stesso anno) nel Paese in cui è stato generato il report. Vengono analizzati i dati degli ultimi 6 mesi.

Prezzo minimo

Prezzo medio


Prezzo massimo

20.334 €

22.251 €

23.776 €

Storico dei prezzi di mercato



Archivio dei prezzi

2023-05 **21.600 €**

2024-04 **24.900 €**

Emissioni

Quanta CO2 emettono i veicoli di questo modello e di quest'anno?

i Nota

Fascia di emissioni di CO2: A (118 g/km)

Emissioni di CO2

Le emissioni di CO2 del

Le emissioni di CO₂ del tuo veicolo

118 g/km Classe **A**

Fino a 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 o superiore

Emissioni di CO₂ g/km

Specifiche e dotazione

Quali sono le specifiche e le dotazioni di questo veicolo?



Nota

Verificare se le specifiche e le dotazioni del veicolo corrispondono a quelle fornite dal venditore.

Identificazione e specifiche tecniche



Fabbricazione

Audi



Modello

Q2



Tipo di carrozzeria

SUV



Anno del modello

2019



Cilindrata del motore

1,6 l



Potenza del motore

85 kW (114 CV)



Tipo di carburante

Diesel



Tipo di trasmissione

Automatico



Tipo di trazione

Trazione anteriore



Colore

Argento



N. Portiere

4



Posizione del volante

Guida a sinistra



N. Cilindri

4



N. Sedili

5

Dotazioni

Come ricevuto dal produttore

0A2

4 DOORS

0AE

FRONT STABILIZER

0B2

WHEELBASE

0BA

WITHOUT REAR STABILIZER

0C0

STANDARD

0EG

INSTALLATION DIFFERENTIATION FOR DUAL-CLUTCH TRANSV. TRANSMISSION DQ200 -- VEHICLE COMPONENTS --

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0LK

WITH SPECIAL PLATES/LABELS/ SAFETY CERTIFICATES FOR ITALY

0MG

VEHICLE CLASS DIFFERENTIATION -GA0-

0N1

STANDARD REAR AXLE

0NA

WITHOUT NAMEPLATE SET (WITHOUT MODEL DESIGNATION)

0P1

REAR SIDE EXHAUST TAILPIPE

0TD

FLOOR MATS IN FRONT AND REAR

0UA

WITHOUT SPECIAL COLOR TRIM

0VG

INFORMATION KIT IN ITALIAN

0Y1

STANDARD CLIMATIC ZONES

0YD

WEIGHT RANGE 4 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G5

SPACE-SAVING SPARE WHEEL, SAME SIZE (SAME ROLLING CIRCUMFERENCE) AS ORIGINAL EQUIPMENT TIRES

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1KE

DISK BRAKES IN REAR

1N7

DYNAMIC STEERING

1PA

STANDARD WHEEL BOLTS

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1T3

FIRST AID KIT WITH WARNING TRIANGLE

1U8

WITHOUT FOLDING TABLE ON FRONT SEAT BACKREST

1W0

WITHOUT REFRIGERATOR/GLOVE COMPARTMENT COOLING SYSTEM

1X0

FRONT WHEEL DRIVE

1XW

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL

1Z0

INITIAL STANDARD FUEL FILLING

1ZE

DISK BRAKES IN FRONT (GEOMET D)

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2H0

WITHOUT "DRIVE SELECT"

2JB

STANDARD BUMPERS

2KS

LABELS/PLATES IN ENGLISH AND ITALIAN

2WA

WITHOUT ADDITIONAL TIRES

2Z8

TYPE SIGN AND COMPANY LOGO

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3CA

WITHOUT PARTITION

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3G0

WITHOUT CHILD SEAT ANCHOR FRONT (ISOFIX)

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3L3

MANUAL HEIGHT ADJUSTMENT FOR FRONT SEATS

3NZ

UNSPLIT REAR SEAT BENCH UNSPLIT, SPLIT FOLDING BACKREST

3S0

WITHOUT ROOF RAILS/ROOF LOAD RACK

3T2

THREE REAR HEAD RESTRAINTS

4A0

WITHOUT SEAT HEATER

4E0

TAILGATE/TRUNK LID UNLOCKING FROM OUTSIDE

4GH

WINDSHIELD IN HEAT-INSULATING GLASS WITH SUNSHIELD

4H3

MANUAL CHILD SAFETY LOCK

4I2

CENTRAL LOCKING WITH RADIO REMOTE CONTROL, INTERIOR RELEASE MECHANISM WITHOUT SAFELOCK

4KC

SIDE AND REAR WINDOWS IN HEAT-INSULATING GLASS

4L2

DIMMING BREAKAWAY INTERIOR REARVIEW MIRROR

4P6

REAR FLOOR PANEL MODULE, TYPE 7

4R4

POWER WINDOWS WITH COMFORT OPERATION AND CIRCUIT BREAKER

4UF

DRIVER AND FRONT PASSENGER AIRBAG WITH FRONT PASSENGER AIRBAG DEACTIVATION

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZE

BLACK MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHz-434.42 MHz

5K5

TRANSIT COATING FILM WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MA

DECORATIVE INSERTS

5RU

RIGHT EXTERIOR MIRROR: CONVEX (LARGE VIEWING FIELD)

5SL

LEFT EXTERIOR MIRROR: ASPHERICAL

5ZF

FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6E3

CENTER ARMREST IN FRONT

6F0

WITHOUT DECORATIVE FILMS / EMBLEMS

6FA

COMPONENTS WITHOUT SPECIAL SURFACE APPEARANCE

6H0

"BASIC"

6K2

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, WITHOUT ADAPTIVE CRUISE CONTROL

6NJ

STANDARD MOLDED HEADLINER

6SS

LUGGAGE COMPARTMENT FLOOR COVERING

6V1

REAR TRIM PANEL (ECE)

6W6

FRONT LICENSE PLATE CARRIER

6XD

EXTERIOR MIRRORS, POWER-ADJUSTABLE/ HEATED

7AA

ELECTRONIC ENGINE IMMOBILIZER

7E6

ELECTRIC AUXILIARY AIR HEATER

7F9

PLASTIC/LEATHER GEARSHIFT KNOB/HANDLE

7G0

WITHOUT PREPARATION FOR VTS (VEHICLE TRACKING SYSTEM)

7HA

WITHOUT LEATHER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M5

WITHOUT PROTECTIVE FILM FOR SCUFF PLATE

7P0

WITHOUT LUMBAR SUPPORT IN SEAT BACKRESTS

7S0

WITHOUT WIND DEFLECTOR

7UF

NAVIGATION SYSTEM - STANDARD

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7X1

PARK DISTANCE CONTROL

7Y0

WITHOUT LANE CHANGE ASSIST

8G0

WITHOUT LIGHT CONTROL

8GU

ALTERNATOR 140 A

8ID

HALOGEN TWIN HEADLAMPS

8K4

SEPARATE DAYTIME RUNNING LIGHTS -- NAR --

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8Q1

HEADLIGHT RANGE ADJUSTMENT

8RM

8 SPEAKERS (PASSIVE)

8SA

TAIL LAMP ASSEMBLIES, STANDARD DESIGN

8T6

CRUISE CONTROL SYSTEM AND SPEED LIMITER

8TB

REAR FOG LAMP

8W1

WASHER FLUID LEVEL INDICATOR

8X0

WITHOUT HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9JA

NON-SMOKER'S PACKAGE

9K0

WITHOUT AIRSCARF

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P9

SEAT BELT REMINDER, ELECTRIC CONTACT IN THE BUCKLE, ADVANCED SAFETY EQUIPMENT

9S5

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"MEDIUM"

9U1

BRAKE PAD WEAR INDICATOR

9ZX

MOBILE PHONE INTERFACE

A00

NO SELF-COLLECTION

A51

AUDI AG

A9F

"ATTRACTION" EQUIPMENT

AQ0

STANDARD-PRODUCTION QUALITY

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B14

TYPE APPROVAL COUNTRY ITALY (SAN MARINO, VATICAN CITY)

C13

OPERATING PERMIT, ALTERATION

DK8

4-CYL. TURBO DIES. ENG. 1.6 L/85 KW 4V TDI COMMON RAIL BASE ENGINE IS TJ1/TI7

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EFO

WITHOUT ECO FUNCTION

EL3

ONLINE SERVICE, WITHOUT OCU, WITH HEAD UNIT CODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EVO

WITHOUT CHARGING CABLE

EW0

WITHOUT MAINTENANCE CONTRACT

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

F32

ALLOY WHEELS 6.5J X 16

FA0

CONTROL OF SERIES PRODUCTION

FC0

WITHOUT CUSTOMIZED INSTALLATION

FM0

BASIC EQUIPMENT VARIANT

FQ0

PRODUCTION WHEELS

G02

SHOCK ABSORPTION IN FRONT

G1C

SEVEN-SPEED AUTOMATIC TRANSMISSION

GB0

WITHOUT BOOSTER

GP0

VEHICLES WITHOUT SPECIAL UPGRADE MEASURES

HI1

TIRES 215/60 R16 95V

I8S

RADIO HIGH SCALE (GEN2)

IT2

WITH AUDI CONNECT PACKAGE 2

IX2

DIESEL ENGINE

J0V

BATTERY 420 A (70 AH)

K4H

CLOSED BODY

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KK3

REFRIGERANT R1234YF

KS0

WITHOUT HEAD-UP DISPLAY

L05

SUSPENSION RANGE 05 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N5B

SEAT TRIM COVERS IN FABRIC

NT0

TRANSIT COATING (TYPE 1)

NZ0

WITHOUT CALL FEATURE

Q1A

STANDARD SEATS IN FRONT

QE0

WITHOUT STORAGE COMPARTMENT PACKAGE/BOX

QG1

SERVICE INTERVAL PROLONGATION

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QJ0

WITHOUT ALUMINUM/CHROME PACKAGE

QK0

WITHOUT MULTIFUNCTION CAMERA

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QV0

WITHOUT TV RECEPTION/DIGITAL RADIO RECEPTION

TJ1

4-CYLINDER DIESEL ENGINE 1.6 L UNIT 04L.1

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UE4

ELECTRIC INTERFACE FOR EXTERNAL USE, AUX-IN AND USB JACK

UH1

PARKING BRAKE

UK1

STANDARD REAR SEAT RELEASE

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VF0

STANDARD PEDAL CLUSTER

VL3

EXTENDED AND PROACTIVE PEDESTRIAN PROTECTION

X4C

EQUIPMENT OPTIONS SUBSET FOR ITALY

Cronologia

6 risultati trovati

La cronologia delle segnalazioni di questo veicolo

Ultime segnalazioni

2019-07

 Paese sconosciuto



È stato immatricolato

Il registro indica un fatto di natura amministrativa. Potrebbe trattarsi di un cambio di proprietà, di documenti, ecc.

2019-08

 Italia



È stato immatricolato

Il registro indica un fatto di natura amministrativa. Potrebbe trattarsi di un cambio di proprietà, di documenti, ecc.

2020-01

 Italia



Cambio di proprietà

Il Paese indicato è la sede di un cambio di proprietà o di un rinnovamento di proprietà documentato. Alcuni cambiamenti possono essere formali, ad esempio trasferimenti di fine contratto e simili.

2023-05

 Italia



Cambio di proprietà

Il Paese indicato è la sede di un cambio di proprietà o di un rinnovamento di proprietà documentato. Alcuni cambiamenti possono essere formali, ad esempio trasferimenti di fine contratto e simili.

2023-05

 Italia



Era in vendita

Questa segnalazione è stato creato perché il veicolo è stato messo in vendita in un determinato mercato. A volte il Paese (o lo Stato) venditore sovrascrive la posizione reale del veicolo.

2024-04

 Italia



Era in vendita


Questa segnalazione è stato creato perché il veicolo è stato messo in vendita in un determinato mercato. A volte il Paese (o lo Stato) venditore sovrascrive la posizione reale del veicolo.



+31

Origine dei dati

Abbiamo controllato 900+ fonti di dati nel **35 Paese**



Partner

Questo report contiene informazioni